

WIPE-OUT CLEANING SOLVENT ACCELERATOR - SHARP SHOOT R 8OZ LIQUID WIPE-OUT ACCELERATOR

[Gun Cleaning & Chemicals](#) > [Solvents & Degreasers](#) > [Bore Solvents](#)

No-Brush Foam Cleans Fast

WIPE-OUT ACCELERATOR™ is extremely easy to use. You wet a patch with WIPE-OUT ACCELERATOR™ and push it through the barrel. While WIPE-OUT ACCELERATOR™ is still wet in the bore you simply apply WIPE-OUT™. Then you patch out after 15 or 20 minutes. WIPE-OUT ACCELERATOR™ is not meant to be used by itself as a cleaner but is a catalyst that enhances the action of WIPE-OUT™. Removal of metal fouling and carbon from the bore can rejuvenate and restore accuracy to and badly fouled firearm. Heavy amounts of brushing to the bore of a firearm can produce damage and un-necessary wear. WIPE-OUT™ and WIPE-OUT ACCELERATOR™ were formulated to utilize technology in the safe removal of all types of fouling from the barrel faster, and more efficiently.....and without brushing. Dissolves copper, bronze, cupro-nickel, brass fouling in the bore twice as fast without brushing. Will protect all metal parts including the bore against corrosion & rust. Totally safe for all steels (both stainless and carbon) Dissolves carbon without brushing Color indicators show the presence of metal fouling, powder fouling and carbon. Odorless, relatively safe, and easy to use. Contains NO ACID and NO AMMONIA.



WIPE-OUT ACCELERATOR™ is extremely easy to use. You wet a patch with WIPE-OUT ACCELERATOR™ and push it through the barrel. While WIPE-OUT ACCELERATOR™ is still wet in the bore you simply apply WIPE-OUT™. Then you patch out after 15 or 20 minutes. WIPE-OUT ACCELERATOR™ is not meant to be used by itself as a cleaner but is a catalyst that enhances the action of WIPE-OUT™. Removal of metal fouling and carbon from the bore can rejuvenate and restore accuracy to and badly fouled firearm. Heavy amounts of brushing to the bore of a firearm can produce damage and un-necessary wear. WIPE-OUT™ and WIPE-OUT ACCELERATOR™ were formulated to utilize technology in the safe removal of all types of fouling from the barrel faster, and more efficiently.....and without brushing. Dissolves copper, bronze, cupro-nickel, brass fouling in the bore twice as fast without brushing. Will protect all metal parts including the bore against corrosion & rust. Totally safe for all steels (both stainless and carbon) Dissolves carbon without brushing Color indicators show the presence of metal fouling, powder fouling and carbon. Odorless, relatively safe, and easy to use. Contains NO ACID and NO AMMONIA.

Attributes

- Name: [SHARP SHOOT R 8OZ LIQUID WIPE-OUT ACCELERATOR](#)
- Manufacturer: [SHARP SHOOT R](#)
- Product no.: 100002539
- Mfr. No.: WAC-800
- Size: 8 oz
- Delivery weight: 0.227kg
- Shipping height: 254mm
- Shipping width: 30mm
- Shipping length: 38mm

- UPC: 695791040047

Item details

Made in USA

Table of Contents

- Startpage
- WIPEOUT ACCELERATOR Safety Instruction Guide
- About Us

WIPEOUT ACCELERATOR Safety Instruction Guide

Introduction

Thank you for choosing WIPEOUT ACCELERATOR™. This product is designed to enhance the cleaning process of your firearm by effectively removing metal fouling and carbon deposits. To ensure safe and effective use, please follow the guidelines and instructions outlined in this safety instruction guide.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose as a cleaning solvent accelerator.
- Keep the product out of reach of children and pets.
- Always use the product in a wellventilated area to avoid inhalation of vapors.
- Avoid contact with skin and eyes. In case of contact, rinse immediately with plenty of water and seek medical attention if necessary.
- Do not ingest the product. If swallowed, seek medical assistance immediately.
- Store the product in a cool, dry place away from direct sunlight and heat sources.
- Check for any visible damage to the product container before use; do not use if damaged.

Specific Safety Precautions for Use

- Always wear appropriate personal protective equipment (PPE) including gloves and safety goggles when handling WIPEOUT ACCELERATOR™.
- Do not mix WIPEOUT ACCELERATOR™ with other cleaning agents or chemicals.
- Use only as directed; do not exceed recommended amounts.
- Allow the product to remain in the bore for no longer than 20 minutes as directed.
- Dispose of used patches and materials properly to avoid environmental contamination.

Instructions for Installation and Usage

1. Preparation:

- Gather all necessary materials including WIPEOUT ACCELERATOR™, cleaning patches, and a cleaning rod.
- Ensure that your firearm is unloaded and pointed in a safe direction.

2. Application:

- Wet a cleaning patch with WIPEOUT ACCELERATOR™.
- Insert the patch into the barrel using a cleaning rod.
- While the bore is still wet with WIPEOUT ACCELERATOR™, apply WIPEOUT™ as per its instructions.
- Allow the product to work for 15 to 20 minutes.

3. Completion:

- After the waiting period, use a clean patch to wipe out the bore.
- Inspect the bore for cleanliness and repeat the process if necessary.

Disposal Instructions

- Dispose of any unused or expired product in accordance with local regulations.
- Used cleaning patches and materials should be disposed of in a sealed bag to prevent environmental contamination.
- Do not pour the product down the drain or dispose of it in regular household waste.

Contact Information for Further Support

For any safety inquiries or further assistance regarding the use of WIPEOUT ACCELERATOR™, please contact your local distributor or refer to the product packaging for additional resources.

By following these instructions and guidelines, you can ensure a safe and effective cleaning experience with WIPEOUT ACCELERATOR™. Thank you for your attention to safety, and enjoy your product!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk