

# TRUE BORE ADI/ACI SET-UP TOOL

[Gunsmith Tools & Supplies](#) > [Sight & Scope Installation Tools](#) > [Scope Reticle Levelers](#)

Bubble level attaches to the muzzle crown to help you calibrate a Flatline Ops ADI, ACI, or other brand angle indicator. When the bubble is between the lines, the barrel is absolutely level, so you know the indicator's reading will be accurate.



## Attributes

- Name: [TRUE BORE ADI/ACI SET-UP TOOL](#)
- Manufacturer: [FLATLINE OPS](#)
- Product no.: 749009107
- Mfr. No.: 60004TB
- Delivery weight: 0.05kg
- Shipping height: 25mm
- Shipping width: 99mm
- Shipping length: 165mm
- UPC: 850020891368

## Item details

Made in USA

# Table of Contents

- Startpage
- FLATLINE OPS TRUE BORE ADI/ACI SETUP TOOL Safety Instructions
- About Us

# FLATLINE OPS TRUE BORE ADI/ACI SETUP TOOL

## Safety Instructions

### Introduction

Thank you for choosing the FLATLINE OPS TRUE BORE ADI/ACI SETUP TOOL. This tool is designed to help you calibrate your angle indicator accurately. Please read this safety instruction guide carefully to ensure safe and effective use of the product.

### General Safety Guidelines

- Ensure that the tool is used only for its intended purpose.
- Always inspect the tool before use for any signs of damage or wear.
- Use the tool in a safe environment, free from distractions and hazards.
- Keep the tool out of reach of children and vulnerable individuals.
- Follow all local laws and regulations regarding the use of this tool.

### Specific Safety Precautions for Use

- Do not use the tool if you are under the influence of drugs or alcohol.
- Ensure that the firearm is unloaded before attaching the bubble level to the muzzle crown.
- Avoid placing your fingers near the muzzle when calibrating the tool.
- Use the tool in a welllit area to ensure accurate readings.
- If the bubble level is not functioning correctly, do not attempt to repair it yourself; consult a professional.

### Instructions for Installation and Usage

#### 1. Preparation

- Ensure that the firearm is unloaded and pointed in a safe direction.
- Gather all necessary tools and materials before starting.

#### 2. Attaching the Bubble Level

- Locate the muzzle crown of your firearm.
- Carefully attach the bubble level to the muzzle crown, ensuring it is secure.

#### 3. Calibrating the Angle Indicator

- Observe the bubble in the level; it should be positioned between the lines.
- If the bubble is not between the lines, adjust the angle of your firearm until it is level.
- Once the bubble is centered, your angle indicator will provide accurate readings.

#### 4. Removing the Tool

- After calibration, carefully remove the bubble level from the muzzle crown.
- Store the tool in a safe, dry place to prevent damage.

### Disposal Instructions

- Dispose of the tool in accordance with local regulations regarding electronic waste.
- If the tool is damaged beyond repair, ensure it is disposed of safely to prevent injury.

## **Contact Information for Further Support**

For any inquiries or concerns regarding the FLATLINE OPS TRUE BORE ADI/ACI SETUP TOOL, please refer to the appropriate contact point provided with your product purchase.

# About Us

## Brownells Austria

**Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

[www.brownells.at](http://www.brownells.at)