

# HEINIE REAR SIGHT CUTTER - CARBIDE HEINIE REAR SIGHT CUTTER

[Gunsmith Tools & Supplies](#) > [Power Tools & Accessories](#) > [Milling Cutters](#)

## 65\ Shoulder x .370"

Cuts the .370 x 65° dovetail required when fitting Heinie rear sights. Solid carbide cuts the hardest slides with minimal wear.



## Attributes

- Name: [CARBIDE HEINIE REAR SIGHT CUTTER](#)
- Manufacturer: [BROWNELLS](#)
- Product no.: 080621371
- Mfr. No.:
- Degree: 65
- Delivery weight: 0.068kg
- Shipping height: 18mm
- Shipping width: 86mm
- Shipping length: 175mm
- UPC: 050806019829

## Item details

Made in USA

# Table of Contents

- Startpage
- HEINIE REAR SIGHT CUTTER CARBIDE Safety Instruction Guide
- About Us

# HEINIE REAR SIGHT CUTTER CARBIDE Safety Instruction Guide

## Introduction

Thank you for choosing the Heinie Rear Sight Cutter Carbide. This tool is designed to help you fit Heinie rear sights by cutting the required .370 x 65° dovetail. Please read this safety instruction guide carefully to ensure safe and effective use of the product.

## General Safety Guidelines

- Always use the cutter in accordance with the manufacturer's instructions.
- Ensure that the work area is clean, welllit, and free from distractions.
- Wear appropriate personal protective equipment (PPE), including safety goggles and gloves.
- Keep the cutter out of reach of children and unauthorized users.
- Regularly inspect the cutter for wear or damage before each use.
- Follow all local regulations and guidelines regarding tool usage and safety.

## Specific Safety Precautions for Use

- Do not attempt to cut materials that exceed the cutter's specifications.
- Avoid using excessive force when cutting; let the cutter do the work.
- Ensure that the workpiece is securely clamped and stable during cutting.
- Never place your hands or any body part near the cutting area while the tool is in operation.
- Always disconnect the cutter from power sources when changing settings or making adjustments.
- In case of malfunction, stop using the cutter immediately and consult a professional.

## Instructions for Installation and Usage

### 1. Preparation:

- Gather all necessary tools and materials before starting.
- Ensure the cutter is clean and free from debris.

### 2. Setup:

- Secure the workpiece in a stable position using clamps.
- Verify that the cutter is properly attached to the milling machine or tool holder.

### 3. Cutting Process:

- Turn on the milling machine and set it to the appropriate speed for carbide cutting.
- Gradually lower the cutter onto the workpiece, ensuring a steady and controlled approach.
- Monitor the cutting process closely and adjust speed as necessary to avoid overheating.

### 4. Finishing:

- Once the cut is complete, turn off the milling machine and allow the cutter to stop completely.
- Carefully remove the workpiece and inspect the cut for accuracy.
- Clean the cutter and work area after use.

## Disposal Instructions

- Dispose of the cutter in accordance with local regulations for hazardous materials.
- Do not dispose of the cutter in regular household waste.
- Consider recycling options where available.

## Contact Information for Further Support

For any safety inquiries or support regarding the Heinie Rear Sight Cutter Carbide, please contact your local distributor or refer to the manufacturer's website for additional resources.

Thank you for your attention to these safety instructions. By following these guidelines, you can ensure a safer and more effective experience with your Heinie Rear Sight Cutter Carbide.

# About Us

## Brownells Austria

**Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

[www.brownells.at](http://www.brownells.at)