

FIELD TRIPOD - SHADOWTECH FIELD TRIPOD

[Optics & Mounting](#) > [Spotting Scopes & Accessories](#) > [Spotting Scope Accessories](#)

Heavy Duty Field Tripod

The ShadowTech PIG0311-G tripod is a no-nonsense field tripod designed for the active outdoorsman. Paired with a direct mounted PIG Saddle, this tripod can do almost anything a more expensive tripod kit can do—at a fraction the cost. The short center column allows the shooter to get all the way down to 11.5-inch high prone position. A removable, load bearing hook has been added to the bottom of the center column to hang weight, such as a backpack. The added weight will greatly increase tripod stability. The tripod's feet incorporate interchangeable rubber or spiked feet (included). Lightweight magnesium body with aluminum legs Three section extending legs with cam levers Lightweight nylon carry bag included Finished off in flat OD Green paint job. The ShadowTech PIG0311-G tripod is sold as the tripod legs alone. A Saddle or ball head would be an additional purchase.



Attributes

- Name: [SHADOWTECH FIELD TRIPOD](#)
- Manufacturer: [SHADOWTECH](#)
- Product no.: 100027653
- Mfr. No.: PIG0311-G
- Max Height: 61"
- Maximum Load Capacity: 26 lbs
- Min Height: 10.8"
- Weight: 5.6 lbs
- Delivery weight: 3.379kg
- Shipping height: 152mm
- Shipping width: 152mm
- Shipping length: 737mm

Table of Contents

- [Startpage](#)
- [ShadowTech PIG0311G Tripod Safety Instruction Guide](#)
- [About Us](#)

ShadowTech PIG0311G Tripod Safety Instruction Guide

Introduction

Thank you for choosing the ShadowTech PIG0311G tripod. This guide provides essential safety information and instructions for the safe use of your tripod. Please read this guide carefully before using the product to ensure a safe and enjoyable experience.

General Safety Guidelines

- Always inspect the tripod before each use for any signs of damage or wear.
- Ensure that the tripod is set up on a stable and level surface to prevent tipping.
- Do not exceed the maximum load capacity of 26 lbs to avoid structural failure.
- Keep the tripod away from children and ensure it is used only by individuals who understand its operation.
- Always use the tripod in accordance with the manufacturer's instructions.
- In the event of an accident or injury, report it to the appropriate authorities.

Specific Safety Precautions for Use

- When extending the legs, do so gradually and ensure that they are locked securely in place.
- Use the removable loadbearing hook to hang weight only if necessary. Ensure that the weight does not exceed the maximum load capacity.
- Be cautious when adjusting the height of the tripod to avoid pinching fingers or hands.
- If using the tripod in windy conditions, consider adding weight to the hook for increased stability.
- When using interchangeable rubber or spiked feet, ensure they are securely attached to prevent slipping.
- Avoid using the tripod near water or in wet conditions to prevent slipping and loss of stability.

Instructions for Installation and Usage

1. Unpacking the Tripod

- Remove the tripod from its carry bag.
- Check all components for damage.

2. Setting Up the Tripod

- Place the tripod on a stable, flat surface.
- Extend the legs to the desired height, ensuring each leg is locked in place.
- If using spiked feet, replace the rubber feet with the spikes as needed.

3. Mounting Equipment

- Attach the PIG Saddle or ball head (sold separately) to the tripod.
- Ensure that the mounted equipment is securely fastened.

4. Adjusting Height

- Loosen the cam levers on each leg to adjust the height.
- Extend or retract each leg to the desired height and lock the levers securely.

5. Using the LoadBearing Hook

- If necessary, hang a weight (such as a backpack) from the loadbearing hook.
- Ensure the total weight does not exceed 26 lbs.

6. Dismantling the Tripod

- Remove any mounted equipment before collapsing the tripod.
- Loosen the cam levers and retract each leg fully.
- Place the tripod back into the carry bag for storage.

Disposal Instructions

- Dispose of the tripod in accordance with local regulations.
- Do not dispose of the tripod in regular household waste if it contains any hazardous materials.
- Consider recycling the materials where possible.

Contact Information for Further Support

For any safety inquiries or further assistance regarding the ShadowTech PIG0311G tripod, please contact the manufacturer or your retailer directly. Ensure you have the product details and any relevant information available for a prompt response.

Thank you for your attention to these safety guidelines. Enjoy your outdoor adventures with the ShadowTech PIG0311G tripod!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk