

# RIFLE BRONZE BORE BRUSH - SINCLAIR INTERNATIONAL 35 CALIBER RIFLE BRONZE BORE BRUSH

[Gun Cleaning & Chemicals](#) > [Brushes & Bore Snakes](#) > [Bore Brushes](#)

Sinclair bronze bore brushes are manufactured significantly larger than bore diameter to fit your barrel properly and have a closed loop on the end. Many other brushes are undersized and don't do an adequate job of scrubbing the barrel.



## Attributes

- Name: [SINCLAIR INTERNATIONAL 35 CALIBER RIFLE BRONZE BORE BRUSH](#)
- Manufacturer: [SINCLAIR INTERNATIONAL](#)
- Product no.: 749000091
- Mfr. No.:
- Caliber: 35 Caliber (.358)
- Delivery weight: 0.032kg
- Shipping width: 83mm
- Shipping length: 146mm

## Item details

Made in USA

# Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for RIFLE BRONZE BORE BRUSH](#)
- [About Us](#)

# Safety Instruction Guide for RIFLE BRONZE BORE BRUSH

## Introduction

Thank you for choosing the RIFLE BRONZE BORE BRUSH by Sinclair International. This guide provides essential safety instructions to ensure safe and effective use of the product. Please read this guide thoroughly before using the bore brush to enhance your shooting experience while ensuring your safety and the safety of others.

## General Safety Guidelines

- Always use the bore brush in accordance with the manufacturer's instructions.
- Keep the product out of reach of children and vulnerable individuals.
- Inspect the bore brush before each use. Do not use if damaged.
- Use protective eyewear when cleaning your firearm.
- Ensure the firearm is unloaded before using the bore brush.
- Be aware of your surroundings and ensure you are in a safe environment when using the bore brush.

## Specific Safety Precautions for Use

- Use the bore brush only for its intended purpose—cleaning the bore of firearms.
- Do not force the brush into the bore; it should fit snugly without excessive pressure.
- Avoid using the bore brush with excessive force to prevent damage to the brush and the firearm.
- After use, clean the bore brush according to the manufacturer's instructions to maintain its effectiveness and longevity.
- Store the bore brush in a cool, dry place, away from moisture and extreme temperatures.

## Instructions for Installation and Usage

### 1. Preparation

- Ensure you have all necessary materials, including the bore brush and a cleaning rod.
- Verify that your firearm is unloaded and in a safe condition.

### 2. Installation

- Attach the bore brush to the cleaning rod securely.
- Ensure that the brush is properly fitted to avoid any accidents during use.

### 3. Usage

- Insert the bore brush into the barrel from the chamber end (if applicable).
- Gently push the brush through the barrel, pulling it out completely before reinserting it.
- Repeat this process as necessary to achieve the desired level of cleanliness.
- After cleaning, remove the bore brush and clean it according to the manufacturer's recommendations.

### 4. PostUsage

- Inspect the bore for any remaining debris or fouling.
- Store the bore brush in its designated location to avoid damage.

## **Disposal Instructions**

- Dispose of any damaged or worn bore brushes in accordance with local regulations.
- Do not dispose of the bore brush in regular household waste if it is contaminated with hazardous materials.
- Consider recycling options where available.

## **Contact Information for Further Support**

For any inquiries regarding safety or product performance, please reach out to the manufacturer's customer service or consult the product's official website for additional resources.

By following these safety instructions, you can ensure a safe and effective cleaning process for your firearm using the RIFLE BRONZE BORE BRUSH. Thank you for prioritizing safety and responsible firearm maintenance.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)