

FUNNEL KIT - MEC RELOADING FUNNEL KIT

[Reloading](#) > [Powder Handling](#) > [Powder Funnel](#)s

The funnel kit is used to pour the powder from the pan of the scale kit into the brass when reloading. Includes two funnels and five sized tubes.



Attributes

- Name: [MEC RELOADING FUNNEL KIT](#)
- Manufacturer: [MEC RELOADING](#)
- Product no.: 749019379
- Mfr. No.: 1089
- Delivery weight: 0.2kg
- Shipping height: 76mm
- Shipping width: 216mm
- Shipping length: 121mm
- UPC: 098489039390

Item details

Made in USA

Table of Contents

- Startpage
- FUNNEL KIT MEC RELOADING FUNNEL KIT Safety Instructions
- About Us

FUNNEL KIT MEC RELOADING FUNNEL KIT Safety Instructions

Introduction

Thank you for choosing the FUNNEL KIT MEC RELOADING FUNNEL KIT. This guide provides essential safety instructions to ensure safe and effective use of the product. Please read this manual carefully before using the funnel kit to understand how to handle it safely.

General Safety Guidelines

- Always handle the funnel kit with care to avoid spills and accidents.
- Ensure that the work area is clean and free from any obstructions or hazards.
- Keep the funnel kit out of reach of children and pets to prevent accidental misuse.
- Inspect the funnel kit before each use for any signs of wear or damage.
- Use the funnel kit only for its intended purpose, which is to pour powder from the scale kit into the brass.
- If you notice any abnormalities during use, stop immediately and assess the situation.

Specific Safety Precautions for Use

- **Personal Protective Equipment (PPE):**
 - Wear safety goggles to protect your eyes from any powder that may escape during pouring.
 - Use gloves to prevent skin contact with the powder.
- **Handling Powder:**
 - Always handle powder in a wellventilated area to avoid inhalation of dust.
 - Avoid using the funnel kit near open flames or sources of ignition.
- **Storage:**
 - Store the funnel kit in a cool, dry place when not in use.
 - Ensure that the funnels and tubes are properly cleaned and dried before storage.

Instructions for Installation and Usage

1. **Preparation:**
 - Gather all necessary materials, including the scale kit and the brass you are reloading.
 - Ensure that the work surface is clean and organized.
2. **Using the Funnel Kit:**
 - Select the appropriate funnel size for the tube you are using.
 - Place the funnel securely into the opening of the brass.
 - Carefully pour the powder from the scale kit into the funnel, allowing it to flow into the brass.
 - Avoid overfilling the brass to prevent spills.
3. **After Use:**
 - Remove the funnel from the brass and clean it thoroughly with a dry cloth.
 - Store the funnel and tubes in their designated storage area.

Disposal Instructions

- Dispose of any unused powder according to local regulations.
- Clean the funnel kit before disposal if it is no longer usable.
- Recycle the funnel kit if possible, following local recycling guidelines.

Contact Information for Further Support

For any questions or concerns regarding the FUNNEL KIT MEC RELOADING FUNNEL KIT, please consult the manufacturer's contact information provided with the product packaging. It is important to have access to support for any safety inquiries or product issues.

Thank you for following these safety instructions. Your safety is our priority, and we hope you have a successful and enjoyable experience with the FUNNEL KIT MEC RELOADING FUNNEL KIT.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk