

Lead Sled Weight Bag, Standard

[Shooting Accessories](#) > [Shooting Rests](#) > [Rifle Rests](#)

These stout bags are designed to be placed in the tray of your Lead Sled® 3, Solo™ or DFT™ 2 and conveniently hold a 25lb bag of lead shot, sand or other weighted media.

NO IMAGE
AVAILABLE

Attributes

- Name: [Lead Sled Weight Bag, Standard](#)
- Manufacturer: [Caldwell](#)
- Product no.: EU1001832
- Mfr. No.: 428334
- Colour: Green
- Delivery weight: 0.14kg
- Shipping height: 142mm
- Shipping width: 56mm
- Shipping length: 226mm
- UPC: 661120283348

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for Caldwell Lead Sled Weight Bag](#)
- [About Us](#)

Safety Instruction Guide for Caldwell Lead Sled Weight Bag

Introduction

Thank you for choosing the Caldwell Lead Sled Weight Bag. This product is designed to enhance the stability of your Lead Sled® 3, Solo™, or DFT™ 2 by securely holding a 25lb bag of lead shot, sand, or other weighted media. To ensure safe and effective use, please read and follow these safety instructions carefully.

General Safety Guidelines

- Ensure that the weight bag is used only with compatible Caldwell products.
- Always inspect the weight bag for any signs of damage before use. Do not use if damaged.
- Keep the weight bag out of reach of children and pets when not in use.
- Store the weight bag in a dry place to prevent deterioration.
- Follow all local regulations regarding the use and disposal of weighted media.

Specific Safety Precautions for Use

- **Weight Limit:** Do not exceed the recommended weight limit of 25lbs for the bag.
- **Surface Stability:** Ensure that the Lead Sled is placed on a stable surface before adding the weight bag.
- **Correct Installation:** Follow the installation instructions carefully to prevent accidents.
- **Avoid Overloading:** Do not attempt to add more than one bag at a time unless specified by the manufacturer.
- **Monitor Use:** Regularly check the weight bag during use for any signs of wear or instability.

Instructions for Installation and Usage

1. Preparation:

- Gather all necessary materials, including the Caldwell Lead Sled and the weight bag.
- Choose a flat, stable surface for setup.

2. Installation:

- Open the tray of your Lead Sled® 3, Solo™, or DFT™ 2.
- Place the Caldwell Lead Sled Weight Bag securely in the tray.
- Ensure that the bag is positioned properly and does not obstruct any moving parts.

3. Adding Weight:

- Carefully fill the weight bag with a 25lb bag of lead shot, sand, or other weighted media.
- Make sure the weight is evenly distributed within the bag.

4. Usage:

- Once the weight bag is installed, check for stability before proceeding with any activities.
- Always monitor the setup during use to ensure everything remains secure.

5. PostUse:

- After use, remove the weight bag and store it in a safe location.
- Inspect the weight bag for any signs of damage and clean if necessary.

Disposal Instructions

- Dispose of any damaged weight bags in accordance with local regulations.
- If using lead shot, ensure that it is disposed of in a manner that complies with environmental safety standards.
- Do not litter; always use designated disposal facilities.

Contact Information for Further Support

For any questions or concerns regarding the Caldwell Lead Sled Weight Bag, please contact the manufacturer or refer to their official website for support.

By following these guidelines, you can ensure a safe and enjoyable experience with your Caldwell Lead Sled Weight Bag. Always prioritize safety and compliance with local regulations. Thank you for your attention to these important safety instructions.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk