

HIGH TEMPERATURE MASKING TAPE - BROWNELLS 1" HIGH TEMP MASKING TAPE

[Gunsmith Tools](#) > [Metal Prep & Coloring](#) > [Paint Finishes](#) > [Painting Accessories](#)

Use With Oven-Cure Finishes - Withstands 400 F Heat

Strong, yet flexible polyester tape withstands sustained temperatures up to 400° F (204° C), making it the perfect masking medium to use with Brownells Baking Lacquer, Gun-Kote™, Teflon®/Moly Oven Cure Gun Finish, and similar oven-cured finishing products. Minimal-bulk, .002" thick polyester backing conforms easily to curves and irregular shapes, yet won't shred when tape is removed. Translucent, so you can see the workpiece underneath as you apply the tape to help you position it precisely. Advanced silicone adhesive grabs tightly and won't pucker, and pulls off clean with no residue.



Attributes

- Name: [BROWNELLS 1" HIGH TEMP MASKING TAPE](#)
- Manufacturer: [BROWNELLS](#)
- Product no.: 080000613
- Mfr. No.: PC211000
- Delivery weight: 0.204kg
- Shipping height: 43mm
- Shipping width: 119mm
- Shipping length: 117mm

Item details

Made in USA

Table of Contents

- Startpage
- HIGH TEMPERATURE MASKING TAPE SAFETY INSTRUCTION GUIDE
- About Us

HIGH TEMPERATURE MASKING TAPE SAFETY INSTRUCTION GUIDE

Introduction

Thank you for choosing the High Temperature Masking Tape from Brownells. This guide provides essential safety information and instructions to ensure safe and effective use of the product. Please read this guide thoroughly before using the tape.

General Safety Guidelines

- Ensure safe use of the tape by following these guidelines:
 - Always store the tape in a cool, dry place away from direct sunlight.
 - Keep the tape out of reach of children and pets.
 - Inspect the tape for any visible damage before use; do not use if damaged.
 - Use the tape only for its intended purpose as described in the product specifications.
 - Be aware of the maximum temperature limit of 400° F (204° C) to avoid product failure.

Specific Safety Precautions for Use

- To ensure safe application and removal of the tape:
 - Always apply the tape to clean, dry surfaces for optimal adhesion.
 - Avoid using the tape on surfaces that are not heatresistant or suitable for hightemperature applications.
 - When removing the tape, do so slowly and carefully to prevent any tearing or shredding.
 - If the tape adheres too strongly, use a heat gun or hairdryer on a low setting to soften the adhesive before removal.
 - Do not use the tape in environments where it may come into contact with open flames or extreme heat sources.

Instructions for Installation and Usage

- Follow these steps for proper installation and usage of the High Temperature Masking Tape:
 1. Prepare the surface by cleaning it thoroughly to remove any dust, grease, or contaminants.
 2. Cut the required length of tape from the roll.
 3. Position the tape on the surface, ensuring it is aligned correctly.
 4. Press down firmly on the tape to ensure good adhesion.
 5. For complex shapes, gently stretch the tape to conform to curves and irregular shapes.
 6. Once the tape is applied, proceed with the application of your finishing product as directed.
 7. After completing your project, carefully remove the tape by pulling it back on itself at a low angle.

Disposal Instructions

- Dispose of the High Temperature Masking Tape responsibly:
 - Do not incinerate the tape.
 - Check local regulations for proper disposal methods for polyester products.
 - If the tape is unused, consider donating it to local community projects or schools.

Contact Information for Further Support

- For safety inquiries or additional support, please reach out to your local EU contact point or regulatory authority.

Conclusion

By following these safety instructions, you can ensure a safe and effective experience with the High Temperature Masking Tape. Always prioritize safety and adhere to the guidelines provided. Thank you for your attention to these important safety measures.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk