

HIGH TEMPERATURE MASKING TAPE - BROWNELLS 2" HIGH TEMP MASKING TAPE

[Gunsmith Tools](#) > [Metal Prep & Coloring](#) > [Paint Finishes](#) > [Painting Accessories](#)

Use With Oven-Cure Finishes - Withstands 400 F Heat

Strong, yet flexible polyester tape withstands sustained temperatures up to 400° F (204° C), making it the perfect masking medium to use with Brownells Baking Lacquer, Gun-Kote™, Teflon®/Moly Oven Cure Gun Finish, and similar oven-cured finishing products. Minimal-bulk, .002" thick polyester backing conforms easily to curves and irregular shapes, yet won't shred when tape is removed. Translucent, so you can see the workpiece underneath as you apply the tape to help you position it precisely. Advanced silicone adhesive grabs tightly and won't pucker, and pulls off clean with no residue.



Attributes

- Name: [BROWNELLS 2" HIGH TEMP MASKING TAPE](#)
- Manufacturer: [BROWNELLS](#)
- Product no.: 080000614
- Mfr. No.: PC212000
- Delivery weight: 0.34kg
- Shipping height: 58mm
- Shipping width: 127mm
- Shipping length: 137mm
- UPC: 050806006461

Item details

Made in USA

Table of Contents

- Startpage
- HIGH TEMPERATURE MASKING TAPE SAFETY INSTRUCTIONS
- About Us

HIGH TEMPERATURE MASKING TAPE SAFETY INSTRUCTIONS

Introduction

Thank you for choosing the HIGH TEMPERATURE MASKING TAPE by Brownells. This product is designed for high-temperature applications, making it an ideal choice for various finishing processes. To ensure safe and effective use, please read this safety instruction guide carefully.

General Safety Guidelines

- Ensure that the tape is used in well-ventilated areas to avoid inhaling any fumes that may arise during application or removal.
- Keep the tape out of reach of children and pets to prevent accidental ingestion or misuse.
- Always check the tape for any visible defects before use. Do not use if the tape is damaged or compromised.
- Store the tape in a cool, dry place away from direct sunlight to maintain its effectiveness and longevity.
- Follow all manufacturer instructions and guidelines for the specific applications of the tape.

Specific Safety Precautions for Use

- Do not use the tape on surfaces that exceed the maximum temperature limit of 400° F (204° C).
- Avoid applying the tape to skin or sensitive areas, as the adhesive may cause irritation upon removal.
- When removing the tape, do so slowly and carefully to minimize the risk of tearing or leaving residue behind.
- If you experience any allergic reactions or skin irritations, discontinue use immediately and consult a medical professional.
- Ensure that the surface to which the tape is applied is clean and free from dust, grease, or moisture to achieve optimal adhesion.

Instructions for Installation and Usage

1. **Preparation:** Clean the surface where the tape will be applied to ensure it is free from contaminants.
2. **Measuring:** Measure the length of tape required for your application and cut it from the roll.
3. **Application:**
 - Start at one end of the area to be masked and press the tape down firmly.
 - Smooth the tape as you apply it to avoid air bubbles and ensure a tight seal.
 - If necessary, use a tool (such as a squeegee) to help press the tape down evenly.
4. **Finishing:** Once the tape is applied, proceed with your finishing process as per the product instructions.
5. **Removal:**
 - Allow the finished product to cool if it has been exposed to high temperatures.
 - Carefully peel the tape away from the surface at a 45-degree angle to minimize residue and damage to the underlying surface.

Disposal Instructions

- Dispose of any unused tape or tape remnants in accordance with local waste disposal regulations.
- Do not incinerate the tape as it may release harmful fumes.
- Consider recycling options if available in your area.

Contact Information for Further Support

For safety inquiries or additional information about the HIGH TEMPERATURE MASKING TAPE, please contact the manufacturer or your retailer directly. Ensure that you have the product details available for reference.

By following these safety instructions, you can ensure a safe and effective experience with the HIGH TEMPERATURE MASKING TAPE. Thank you for your attention to these guidelines.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk