

PERFECT POWDER MEASURE - LEE PRECISION PERFECT POWDER MEASURE

[Reloading](#) > [Powder Handling](#) > [Powder Measures & Dispensers](#)

Best for reloading rifle cases, can also be used for pistol cases Throws charges from 2 to over 100 grains Includes a sturdy steel stand for bench mounting Micrometer adjustable

Best for reloading rifle cases, can also be used for pistol cases Throws charges from 2 to over 100 grains Includes a sturdy steel stand for bench mounting Micrometer adjustable



Attributes

- Name: [LEE PRECISION PERFECT POWDER MEASURE](#)
- Manufacturer: [LEE PRECISION](#)
- Product no.: 100010145
- Mfr. No.: 90058
- Delivery weight: 0.408kg
- Shipping height: 84mm
- Shipping width: 130mm
- Shipping length: 244mm
- UPC: 734307900588

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for the PERFECT POWDER MEASURE by LEE PRECISION
- About Us

Safety Instruction Guide for the PERFECT POWDER MEASURE by LEE PRECISION

Introduction

Thank you for choosing the PERFECT POWDER MEASURE by LEE PRECISION. This guide provides essential safety instructions and information to ensure the safe and effective use of your powder measure. Please read this guide carefully before using the product.

General Safety Guidelines

- Always follow the manufacturer's instructions for safe use.
- Inspect the powder measure for any damage before use.
- Keep the product out of reach of children and vulnerable individuals.
- Use the product only for its intended purpose—reloading rifle and pistol cases.
- Ensure that your working area is clean, welllit, and free from distractions.
- Wear appropriate personal protective equipment (PPE), such as safety glasses and gloves, when handling powders and reloading materials.
- Be aware of your surroundings and avoid using the product in a crowded or confined space.

Specific Safety Precautions for Use

- Do not exceed the recommended charge weights as specified in the reloading manual.
- Ensure that the powder measure is securely mounted to the bench stand before use.
- Never leave the powder measure unattended while in operation.
- Avoid direct contact with powders and ensure that any spills are cleaned up immediately.
- Do not use the powder measure if you are under the influence of drugs or alcohol.
- If you experience any discomfort or adverse reactions while using the product, stop immediately and seek medical attention if necessary.

Instructions for Installation and Usage

1. Installation:

- Select a stable and flat surface for mounting the powder measure.
- Use the included sturdy steel stand to securely mount the powder measure to your workbench.
- Ensure that the powder measure is level and stable before proceeding.

2. Usage:

- Adjust the micrometer to the desired charge weight according to your reloading specifications.
- Fill the powder reservoir with the appropriate powder, ensuring that it is clean and free from moisture.
- Place an empty case under the discharge spout of the powder measure.
- Activate the measure to dispense the powder charge into the case.
- Check the weight of the charge using a reliable scale to ensure accuracy.
- Repeat the process as needed, ensuring that you follow all safety precautions.

Disposal Instructions

- Dispose of any unused powder and materials according to local regulations for hazardous waste.
- Do not dispose of powders in regular trash or down the drain.
- Follow your local guidelines for the safe disposal of reloading materials.

Contact Information for Further Support

For any questions or concerns regarding the use of the PERFECT POWDER MEASURE, please refer to the manufacturer's official website or contact their customer support for assistance.

By following these safety instructions, you can ensure a safe and enjoyable reloading experience with your PERFECT POWDER MEASURE by LEE PRECISION. Always prioritize safety and stay informed about best practices in reloading.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk