

POWDER MEASURE STAND - LEE PRECISION POWDER MEASURE STAND

[Reloading](#) > [Powder Handling](#) > [Measure Stands & Accessories](#)

A real powder measure stand, not a cast or stamped bracket. No need to bolt or screw this beefy stand to your work bench. Heavy powder coated steel stand compliments any brand or color powder measure. Works especially well with other brands of powder measures that don't have Lee's on/off valve or removable hopper feature. When you want to change powders or empty the hopper. Simply lift the stand and you can pour the powder from your measure. When you're finished, store your measure away freeing up valuable bench space. Powder coated steel construction. 7/8" mounting hole for all popular measures. Includes 3 no slip feet. Rock solid mount improves measure consistency. Space saving freestanding design is portable and convenient.



Attributes

- Name: [LEE PRECISION POWDER MEASURE STAND](#)
- Manufacturer: [LEE PRECISION](#)
- Product no.: 100018927
- Mfr. No.: 90587
- Delivery weight: 1.395kg
- Shipping height: 140mm
- Shipping width: 171mm
- Shipping length: 178mm
- UPC: 734307905873

Item details

Made in USA

Table of Contents

- Startpage
- POWDER MEASURE STAND Safety Instruction Guide
- About Us

POWDER MEASURE STAND Safety Instruction Guide

Introduction

Thank you for purchasing the POWDER MEASURE STAND by Lee Precision. This guide provides essential safety instructions to ensure the safe use and maintenance of your powder measure stand. Please read this guide carefully to understand how to use the product safely and effectively.

General Safety Guidelines

- Always ensure the stand is placed on a stable and level surface to prevent tipping.
- Keep the area around the stand clean and free from clutter to avoid accidents.
- Use the stand only for its intended purpose - supporting powder measures.
- Always handle powders with care and follow manufacturer guidelines for safe handling.
- Store the powder measure stand in a dry place when not in use.
- Regularly inspect the stand for signs of wear or damage before each use.

Specific Safety Precautions for Use

- Ensure that the powder measure is securely mounted on the stand before use.
- Do not attempt to modify or alter the stand in any way.
- Avoid using the stand near open flames or high heat sources.
- Keep the stand and powder measures out of reach of children and pets.
- If you experience any issues or instability while using the stand, cease use immediately and inspect for problems.

Instructions for Installation and Usage

1. Installation:

- Place the stand on a flat, stable surface.
- Ensure that the 7/8" mounting hole aligns with the base of your powder measure.
- Securely attach the powder measure to the stand using the appropriate mounting hardware (not included).
- Ensure the stand is stable and does not wobble before use.

2. Usage:

- When changing powders or emptying the hopper, lift the stand carefully to pour out the powder.
- Avoid overfilling the powder measure to prevent spills.
- After use, store the powder measure and stand in a safe place to free up bench space.

Disposal Instructions

- Dispose of the product in accordance with local waste management regulations.
- If the stand is damaged beyond repair, recycle the metal components where possible.
- Do not dispose of any powders or hazardous materials with general waste.

Contact Information for Further Support

For any inquiries regarding safety or product issues, please refer to the manufacturer's contact details provided

with your product.

Thank you for choosing the POWDER MEASURE STAND by Lee Precision. Your safety is our priority, and we hope you enjoy using your new product responsibly.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk