

M-LOK ADAPTER FOR ATLAS® BIPODS - ACCU-SHOT M-LOK ADAPTER FOR ATLAS BIPODS BLACK

[Shooting Accessories](#) > [Bipods, Monopods & Accessories](#) > [Bipod Accessories](#)

ATLAS BIPOD® M-LOK ADAPTER FOR ATLAS® BIPODS The BT70 Atlas M-LOK® Adapter is an interface between all Atlas bipods with the “NC” designator in their names (BT10-NC, BT46-NC, BT47-NC, BT35-NC, BT65-NC, BT69-NC, BT72-NC) and M-LOK style mounting systems. It requires two (2) M-LOK standard sized slots for mounting. Machined from 6061-T6 aluminum and Type III hard coat anodized and comes with two 3/8 fasteners and two M-LOK nuts. Available in black only. SPECS Length: 3.15" Width: 1.11" Weight: 1.135 oz"



Attributes

- Name: [ACCU-SHOT M-LOK ADAPTER FOR ATLAS BIPODS BLACK](#)
- Manufacturer: [ACCU-SHOT](#)
- Product no.: 100041874
- Mfr. No.: BT70
- Delivery weight: 0.041kg
- Shipping height: 6mm
- Shipping width: 140mm
- Shipping length: 140mm
- UPC: 810040220647

Item details

Made in USA

Table of Contents

- Startpage
- MLOK Adapter for Atlas Bipods Safety Instructions
- About Us

MLOK Adapter for Atlas Bipods Safety Instructions

Introduction

Thank you for choosing the MLOK Adapter for Atlas Bipods. This product is designed to enhance the functionality of your Atlas bipods by providing a secure interface with MLOK style mounting systems. Please read this safety instruction guide carefully to ensure safe and effective use of the product.

General Safety Guidelines

- Ensure the product is used only for its intended purpose as described in this manual.
- Regularly inspect the adapter for any signs of wear or damage before each use.
- Keep the adapter and all components out of reach of children and vulnerable individuals.
- Follow all installation and usage instructions to minimize risks of accidents or injuries.
- Report any unsafe products or accidents to the relevant authorities.

Specific Safety Precautions for Use

- Do not exceed the weight limit of your bipod when using the adapter.
- Ensure that the adapter is securely mounted before attaching any equipment.
- Avoid using the adapter in adverse weather conditions that may affect stability or safety.
- Use only the provided fasteners and MLOK nuts for installation to ensure compatibility.
- Do not modify the adapter or use it in any manner not specified in the product instructions.

Instructions for Installation and Usage

1. Installation

- Ensure that you have two standardsized MLOK slots available for mounting.
- Align the MLOK adapter with the MLOK slots on your mounting surface.
- Insert the provided MLOK nuts into the slots and position them against the adapter.
- Use the provided 3/8 fasteners to secure the adapter in place.
- Tighten the fasteners until the adapter is firmly attached, but do not overtighten.

2. Usage

- After installation, ensure the adapter is stable and secure before attaching your bipod.
- Attach your Atlas bipod with the “NC” designator (e.g., BT10NC, BT46NC) to the adapter.
- Confirm that the bipod is securely locked in place before use.
- To detach the bipod, reverse the attachment process carefully.

Disposal Instructions

- Dispose of the MLOK adapter and all packaging materials in accordance with local regulations.
- Do not dispose of the product in household waste. Instead, utilize designated recycling facilities or electronic waste disposal services if applicable.

Contact Information for Further Support

For any inquiries regarding safety, installation, or product performance, please refer to the manufacturer's contact point provided with your product packaging. It is essential to reach out for support to ensure the safe

use of your MLOK Adapter for Atlas Bipods.

By following these guidelines, you can ensure a safe and enjoyable experience with your MLOK Adapter. Thank you for your attention to safety and for choosing our product.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk