

# BORE-MAX SPEED JAG & PATCH COMBO - REAL AVID 270 CALIBER

## BORE-MAX JAG & BORE-MAX SPEED PATCHES 25CT

[Gun Cleaning & Chemicals](#) > [Cleaning Rods & Accessories](#) > [Cleaning Rod Jags](#)

Bore-Max Speed Jag and Patches are components of the Bore-Max Speed Clean System for faster and easier bore cleaning. Within the bore, carbon and copper fouling build-up in layers over time and cumulatively have a significant impact on a firearms performance if left unchecked. The carbon build-up essentially insulates the copper fouling from the outside in. Carbon layers need to be removed mechanically with a bore brush in order to fully expose the copper layers beneath. Alternately, copper must be chemically dissolved in order to remove it from the bore, as a brush is ineffective at breaking loose these heat-melded deposits. Sized to account precisely for both the jag diameter and patch thickness this Speed Jag and Patch combo provides the optimal compression to thoroughly and consistently reach into the lands and grooves. Tight enough to provide superior compression within the bore while still remaining relatively easy to push through. The Speed Jag and Patch system gets more patch material in the bore, eliminates bunching and maximizes the effectiveness of each pass-through. Speed Patches are a synthetic material that has shown to have superior absorbency over cotton. This material is better at absorbing fouling and spent solvent in the bore and is more effective at picking up and trapping crud.



### Attributes

- Name: [REAL AVID 270 CALIBER BORE-MAX JAG & BORE-MAX SPEED PATCHES 25CT](#)
- Manufacturer: [REAL AVID](#)
- Product no.: 100047687
- Mfr. No.: AVBMJAG270
- Caliber: 270 Caliber
- Delivery weight: 0.045kg
- Shipping height: 13mm
- Shipping width: 70mm
- Shipping length: 171mm
- UPC: 813119013539

# Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for BOREMAX SPEED JAG & PATCH COMBO](#)
- [About Us](#)

# Safety Instruction Guide for BOREMAX SPEED JAG & PATCH COMBO

## Introduction

Thank you for choosing the BOREMAX SPEED JAG & PATCH COMBO. This product is designed to help you clean your firearm's bore efficiently and effectively. To ensure your safety and the proper use of this product, please read and follow the instructions and guidelines provided in this manual.

## General Safety Guidelines

- Always ensure that your firearm is unloaded before cleaning.
- Keep the cleaning components out of reach of children and pets.
- Use the product only for its intended purpose as described in this manual.
- Inspect the product for any damage before use. Do not use if damaged.
- Store the product in a cool, dry place away from direct sunlight.
- Report any unsafe product conditions or accidents to the appropriate authorities.
- Stay informed about product recalls and safety updates through the EU Safety Gate platform.

## Specific Safety Precautions for Use

- Ensure that you are in a wellventilated area when using cleaning solvents.
- Wear protective gloves and eyewear to avoid contact with solvents and cleaning agents.
- Avoid prolonged exposure to cleaning solvents. Follow the manufacturer's safety data sheets for solvents used with this product.
- Do not use excessive force when pushing the jag and patch through the bore to avoid damaging the firearm.
- Always follow the manufacturer's instructions for solvent use and disposal.

## Instructions for Installation and Usage

### 1. Preparation

- Ensure your firearm is completely unloaded.
- Gather all necessary cleaning supplies, including the BOREMAX SPEED JAG, PATCHES, and your preferred solvent.

### 2. Attaching the Jag

- Select the appropriate jag size for your firearm's caliber (in this case, 270 Caliber).
- Firmly attach the jag to the cleaning rod, ensuring it is securely fastened.

### 3. Preparing the Patch

- Take a BOREMAX SPEED PATCH and place it over the jag.
- Ensure the patch is centered and covers the jag completely.

### 4. Applying Solvent

- Apply a small amount of solvent to the patch, ensuring it is evenly saturated but not dripping.

### 5. Cleaning the Bore

- Insert the jag with the patch into the bore.

- Push the cleaning rod through the bore with a steady, gentle motion.
- Avoid using excessive force; let the patch do the work.
- Repeat the process as needed until the bore is clean.

#### **6. PostCleaning**

- After cleaning, remove the jag and discard the used patch.
- Clean the jag and rod according to the manufacturer's instructions.
- Store the product in a safe place.

## **Disposal Instructions**

- Dispose of used patches and any cleaning solvents according to local regulations.
- Do not dispose of cleaning materials in regular household waste unless specified safe to do so.
- Check with local waste management for proper disposal methods for hazardous materials.

## **Contact Information for Further Support**

For any questions or concerns regarding the BOREMAX SPEED JAG & PATCH COMBO, please contact the manufacturer or your local retailer for assistance. Ensure to have your product details available for reference.

By following these guidelines, you can safely and effectively use the BOREMAX SPEED JAG & PATCH COMBO for your firearm cleaning needs. Thank you for your attention to safety.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)