

IMPROVED POWDER MEASURE KIT - LEE PRECISION LEE POWDER MEASURE KIT

[Reloading](#) > [Powder Handling](#) > [Powder Measures & Dispensers](#)

Lee Powder Measure Dipper Kit includes 15 graduated powder dippers from .3cc to 4.3cc. Slide card included has powder dispensing chart.



Attributes

- Name: [LEE PRECISION LEE POWDER MEASURE KIT](#)
- Manufacturer: [LEE PRECISION](#)
- Product no.: 100053443
- Mfr. No.: 90100
- Delivery weight: 0.181kg
- Shipping height: 42mm
- Shipping width: 140mm
- Shipping length: 434mm
- UPC: 734307901004

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for the Improved Powder Measure Kit
- About Us

Safety Instruction Guide for the Improved Powder Measure Kit

Introduction

Thank you for purchasing the Improved Powder Measure Kit from Lee Precision. This guide provides essential safety instructions to ensure the safe and effective use of the product. Please read this guide carefully before using the kit.

General Safety Guidelines

- Always use the product in accordance with the manufacturer's instructions.
- Keep the product out of reach of children and vulnerable individuals to prevent accidents.
- Inspect the kit for any damage before use. Do not use if any components are damaged.
- Report any unsafe conditions or accidents to the relevant authorities immediately.
- Stay informed about product recalls and safety updates through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Ensure that you are using the correct powder dipper for the amount of powder required.
- Avoid inhaling powder particles. Use in a wellventilated area.
- Do not use the dippers for any purpose other than their intended use.
- Handle all powders with care, following the manufacturer's safety data sheets.
- Wear appropriate personal protective equipment (PPE), such as gloves and safety glasses, when handling powders.

Instructions for Installation and Usage

1. Unpacking the Kit

- Carefully remove the kit from its packaging.
- Check that all components are present: 15 graduated powder dippers and the slide card with the powder dispensing chart.

2. Selecting the Correct Dipper

- Choose a dipper based on the required volume of powder. The dippers range from .3cc to 4.3cc.
- Refer to the slide card for guidance on the appropriate dipper size for your needs.

3. Measuring Powder

- Fill the selected dipper with powder, ensuring it is level with the top.
- Avoid overfilling to prevent spills and ensure accuracy.

4. Dispensing Powder

- Carefully pour the measured powder into the desired container or loading device.
- Avoid direct contact with the powder and ensure that you are in a safe environment.

5. Cleaning and Maintenance

- After use, clean the dippers with a soft brush or cloth to remove any residual powder.
- Store the kit in a cool, dry place to prevent damage or contamination.

Disposal Instructions

- Dispose of any unused or expired powders according to local regulations.
- Recycle packaging materials where possible.
- Do not dispose of powders or dippers in the general waste. Follow hazardous waste disposal guidelines if applicable.

Contact Information for Further Support

For any inquiries regarding safety or product performance, please consult the appropriate EUbased contact point or customer service for assistance.

Thank you for your attention to these safety instructions. Your safety is our priority, and we hope you enjoy using the Improved Powder Measure Kit.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk