

38 S&W COWBOY DIE SET - RCBS 38 S&W 3-DIE SET

[Reloading](#) > [Reloading Dies](#) > [Handgun Dies](#)

RCBS' 38 S&W 3-Die Cowboy Dies are built to slightly different dimensions than their regular dies to allow optimum sizing, expanding and crimping needed to load great lead bullet ammo. The 3-Die Carbide Roll Crimp Set is intended for loading straight-wall cartridges for period firearms used in Cowboy Action Shooting. The design allows optimum sizing, expanding, seating and crimping for lead bullet ammunition.



Attributes

- Name: [RCBS 38 S&W 3-DIE SET](#)
- Manufacturer: [RCBS](#)
- Product no.: 100060490
- Mfr. No.: 20351
- Cartridge: 38 S&W
- Delivery weight: 0.828kg
- Shipping height: 38mm
- Shipping width: 114mm
- Shipping length: 152mm
- UPC: 076683203519

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for RCBS 38 S&W 3Die Cowboy Die Set](#)
- [About Us](#)

Safety Instruction Guide for RCBS 38 S&W 3Die Cowboy Die Set

Introduction

Thank you for choosing the RCBS 38 S&W 3Die Cowboy Die Set. This guide provides important safety information and instructions to ensure the safe use of your die set. Please read this guide carefully before use to ensure your safety and the proper functioning of the product.

General Safety Guidelines

- Ensure that the die set is used only for its intended purpose: loading lead bullet ammunition for Cowboy Action Shooting.
- Always wear appropriate safety gear, including safety glasses and hearing protection, when reloading ammunition.
- Keep the die set and all reloading components out of reach of children and unauthorized users.
- Inspect the die set regularly for signs of wear or damage. Do not use damaged components.
- Follow all local laws and regulations regarding ammunition reloading and usage.

Specific Safety Precautions for Use

- Ensure that your work area is clean, dry, and well lit.
- Do not operate the die set if you are under the influence of drugs or alcohol.
- Always double check that you are using the correct components for the 38 S&W cartridge.
- Use only recommended powders and primers for reloading to avoid dangerous reactions.
- Avoid overloading cartridges. Follow published load data from reputable sources.
- Be aware of the risk of lead exposure. Use proper ventilation and wash hands thoroughly after handling lead materials.
- Never point a firearm at yourself or others when using reloaded ammunition.

Instructions for Installation and Usage

1. Setup the Die Set:

- Securely mount the die set in a reloading press according to the manufacturer's instructions.
- Ensure that the dies are properly adjusted for the 38 S&W cartridge dimensions.

2. Reloading Process:

- Start by resizing the cartridge cases using the sizing die.
- Next, expand the case mouths using the expanding die to prepare for bullet seating.
- Seat the lead bullets into the prepared cases using the seating die, ensuring the correct depth.
- Finally, crimp the bullets using the crimping die to secure them in place.

3. Post Reloading:

- Inspect each cartridge for proper seating and crimp.
- Store reloaded ammunition in a cool, dry place, away from direct sunlight.

Disposal Instructions

- Dispose of any unused or outdated reloading materials according to local regulations.
- Do not dispose of lead materials in regular trash. Check for local recycling programs that accept lead.

Contact Information for Further Support

For any questions or concerns regarding the safety or use of the RCBS 38 S&W 3Die Cowboy Die Set, please refer to the manufacturer's contact information included with your product packaging.

By following these guidelines and instructions, you can ensure a safe and enjoyable reloading experience with your RCBS 38 S&W 3Die Cowboy Die Set. Thank you for prioritizing safety in your reloading practices.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk