

CZ P10C VORTEX RAZOR SIGHT MOUNT - EGW CZ P10C VORTEX RAZOR SIGHT MOUNT

[Optics & Mounting](#) > [Rings, Mounts & Bases](#) > [Handgun Bases](#)

Material: 7075 Aluminum Coating: Matte Black Hardcoat Overall Length: 1.831" Overall Width: 1.062" Mounting Hardware: (2) 8-32 Button Head Screws, (1) 8-32 Set Screw) Red Dot Fitment: Vortex Razor, C-More RTS & STS Simply remove the rear sight on your gun and replace it with our mount in order to mount your Vortex Razor, C-More RTS or STS red-dot sight. No alterations are required. You can take our mount off and replace your rear sight at any time. Mounting hardware included. Installation Instructions Remove the rear sight* Install the EGW Sight Mount in the dovetail Tighten set screw (if applicable) Place the red dot sight on the EGW Sight Mount (placing a small piece of paper between the red dot sight and the sight mount will make for easier removal and will keep Loctite off of the red dot sight.) Apply blue Loctite to the provided mounting screws Torque mounting screws to 15in/lbs



Attributes

- Name: [EGW CZ P10C VORTEX RAZOR SIGHT MOUNT](#)
- Manufacturer: [EGW](#)
- Product no.: 296000557
- Mfr. No.: 49462
- Colour: Black
- Material: Aluminum
- Model: P-10 Compact
- Number of Bases: 1-Piece
- Style: Tactical
- Weapon type: CZ
- Delivery weight: 0.037kg
- Shipping height: 25mm
- Shipping width: 89mm
- Shipping length: 133mm
- UPC: 841370117048

Item details

Made in USA

Table of Contents

- Startpage
- CZ P10C Vortex Razor Sight Mount Safety Instruction Guide
- About Us

CZ P10C Vortex Razor Sight Mount Safety Instruction Guide

Introduction

Thank you for choosing the CZ P10C Vortex Razor Sight Mount by EGW. This guide provides essential safety instructions, installation procedures, and usage recommendations to ensure the safe operation of your sight mount. Please read this guide carefully before use.

General Safety Guidelines

- Ensure that the product is suitable for your firearm model, specifically the CZ P10C.
- Always handle firearms and accessories with care, following all local laws and regulations.
- Inspect the sight mount for any visible damage before installation. Do not use if damaged.
- Only use the recommended mounting hardware provided with the sight mount.
- Keep the product out of reach of children and unauthorized users.
- Report any unsafe products or accidents to local authorities.

Specific Safety Precautions for Use

- Always ensure the firearm is unloaded before installing or removing the sight mount.
- Avoid using excessive force when tightening screws to prevent damage to the sight mount or firearm.
- Use blue Loctite as instructed to secure the mounting screws, ensuring they do not loosen during use.
- If you experience any difficulty during installation or usage, cease use immediately and seek assistance.
- Regularly check the tightness of the mounting screws to ensure secure attachment.

Instructions for Installation and Usage

1. Remove the Rear Sight

- Carefully remove the rear sight from your CZ P10C firearm.

2. Install the EGW Sight Mount

- Place the EGW Sight Mount into the dovetail where the rear sight was removed.
- Ensure it is properly aligned.

3. Tighten the Set Screw

- If applicable, tighten the set screw to secure the sight mount in place.

4. Attach the Red Dot Sight

- Place your Vortex Razor, CMORE RTS, or STS red dot sight on the EGW Sight Mount.
- For easier removal, place a small piece of paper between the red dot sight and the sight mount to prevent Loctite from adhering to the sight.

5. Apply Blue Loctite

- Apply blue Loctite to the provided mounting screws.

6. Torque Mounting Screws

- Tighten the mounting screws to a torque of 15 in/lbs.

Disposal Instructions

- Dispose of the sight mount and any packaging materials in accordance with local regulations.
- Do not dispose of the product in household waste. Instead, use designated recycling facilities where available.

Contact Information for Further Support

For any inquiries regarding the safety or usage of the CZ P10C Vortex Razor Sight Mount, please reach out to the appropriate support channels. Ensure you have the product information readily available for assistance.

Thank you for your attention to these safety instructions. By following these guidelines, you can ensure a safe and effective experience with your CZ P10C Vortex Razor Sight Mount.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk