

NO. BV-N & BV-W BORDER-VEX REPLACEMENT CUTTER - GUNLINE BV-W BORDER VEX

[Gunsmith Tools & Supplies](#) > [Stock Work & Finishing](#) > [Hand Checkering Tools](#) > [Checkering Cutters](#)

Gunline Replacement Cutters, Less Handles; Fits All Gunline Handles

Cut a convex border around the pattern. Erases overruns. BV-N (narrow) comes in 20-28 lpi sets, BV-W (wide) comes in 18 lpi sets. BV-XW (extra-wide) comes in 16 lpi sets. 60°



Attributes

- Name: [GUNLINE BV-W BORDER VEX](#)
- Manufacturer: [GUNLINE](#)
- Product no.: 364105602
- Mfr. No.: BVW
- Size: 18
- Delivery weight: 0.005kg
- UPC: 818262200362

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER](#)
- [About Us](#)

Safety Instruction Guide for NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER

Introduction

Thank you for choosing the NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER by GUNLINE. This guide provides important safety information and instructions to ensure the safe and effective use of your cutter. Please read this guide carefully before using the product.

General Safety Guidelines

- Always use the cutter in accordance with the manufacturer's instructions.
- Ensure that the cutter is suitable for the task at hand, particularly with regard to the size and type of border you wish to create.
- Keep the cutter out of reach of children and vulnerable individuals.
- Inspect the cutter before use to ensure it is in good working condition. Do not use if damaged.
- Use personal protective equipment, such as safety glasses and gloves, when operating the cutter.
- Be aware of your surroundings and ensure that the work area is clear of obstacles and bystanders.

Specific Safety Precautions for Use

- Do not apply excessive force when cutting, as this may lead to loss of control and potential injury.
- Use the cutter only on appropriate materials as specified by the manufacturer.
- Avoid using the cutter near water or in wet conditions to prevent electrical hazards if applicable.
- Do not attempt to modify or repair the cutter yourself. Contact a qualified technician for repairs.
- Always store the cutter in a safe place when not in use, preferably in a protective case.

Instructions for Installation and Usage

1. Preparation:

- Ensure you have the correct cutter size for your project: BVN (narrow), BVW (wide), or BVXW (extrawide).
- Gather your materials and tools before starting the cutting process.

2. Installation:

- Follow the manufacturer's instructions for attaching the cutter to any necessary equipment.
- Ensure all components are securely fastened before use.

3. Usage:

- Position the cutter at the starting point of your desired convex border.
- Apply steady pressure while moving the cutter along the intended path, ensuring you maintain control.
- If you experience difficulty or resistance, stop and check for any obstructions or damage to the cutter.
- After completing the cut, carefully remove any excess material and inspect the work area for any leftover debris.

Disposal Instructions

- Dispose of the cutter in accordance with local regulations regarding electronic and sharp objects.
- If the cutter is no longer functional, consider recycling it at a designated electronic waste facility.
- Ensure that the cutter is not accessible to children during the disposal process.

Contact Information for Further Support

For any safety inquiries or further assistance regarding the NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER, please refer to the contact information provided with your product packaging.

Conclusion

By following these safety guidelines and instructions, you can ensure a safe and effective experience with your NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER. Always prioritize safety and do not hesitate to seek help if you have any questions or concerns about the product.

About Us

Brownells Europe

Brownells Europe - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

P.O.Box 4300
Warwick
CV34 9BR

www.brownells.eu