

NO. BV-N & BV-W BORDER-VEX REPLACEMENT CUTTER - GUNLINE BV-XW BORDER VEX

[Gunsmith Tools & Supplies](#) > [Stock Work & Finishing](#) > [Hand Checkering Tools](#) > [Checkering Cutters](#)

Gunline Replacement Cutters, Less Handles; Fits All Gunline Handles

Cut a convex border around the pattern. Erases overruns. BV-N (narrow) comes in 20-28 lpi sets, BV-W (wide) comes in 18 lpi sets. BV-XW (extra-wide) comes in 16 lpi sets. 60°



Attributes

- Name: [GUNLINE BV-XW BORDER VEX](#)
- Manufacturer: [GUNLINE](#)
- Product no.: 364105603
- Mfr. No.: BVXW
- Size: 16
- Delivery weight: 0.005kg
- UPC: 818262200393

Item details

Made in USA

Table of Contents

- Startpage
- Safety Instruction Guide for NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER
- About Us

Safety Instruction Guide for NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER

Introduction

Thank you for choosing the NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER by GUNLINE. This guide provides essential safety instructions to ensure the safe and effective use of the product. Please read this guide carefully before using the cutter.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose: cutting convex borders around patterns.
- Keep the product out of reach of children and vulnerable individuals.
- Inspect the cutter before each use to ensure it is in good condition and free from damage.
- If you notice any defects or issues, do not use the product and contact the manufacturer for support.
- Always follow local regulations and guidelines regarding the use of cutting tools.

Specific Safety Precautions for Use

- Always wear appropriate personal protective equipment (PPE), including safety glasses and gloves, when using the cutter.
- Make sure your workspace is clean and free from clutter to avoid accidents.
- Use the cutter on a stable surface to prevent slipping or movement during use.
- Do not apply excessive force when cutting; let the cutter do the work to avoid injury.
- Keep your fingers and hands away from the cutting area to prevent cuts or injuries.
- Store the cutter in a safe place when not in use, ensuring the blade is covered or protected.

Instructions for Installation and Usage

1. Preparation:

- Ensure that the work area is welllit and organized.
- Gather all necessary materials, including the cutter and the pattern you will be cutting.

2. Installation:

- If applicable, install the cutter according to the manufacturer's instructions. Ensure all components are securely attached.

3. Usage:

- Position the pattern on a flat, stable surface.
- Align the cutter along the edge of the pattern where you want to create the convex border.
- Apply gentle pressure to the cutter and move it along the edge in a smooth motion.
- For narrow (BVN), wide (BVW), or extrawide (BVXW) cuts, ensure you are using the correct cutter for your desired line per inch (lpi).
- After completing the cut, carefully remove the cutter from the pattern.

4. PostUsage:

- Clean the cutter after use to maintain its effectiveness and longevity.
- Store the cutter in a safe location, ensuring that it is out of reach of children.

Disposal Instructions

- Dispose of the cutter responsibly according to local regulations for hazardous materials.
- If the cutter is no longer usable, ensure it is disposed of in a way that minimizes risk to others, such as wrapping it securely before disposal.

Contact Information for Further Support

For any questions or concerns regarding the NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER, please refer to the manufacturer's contact information provided in the product packaging or visit the manufacturer's website for additional resources.

By following these guidelines, you can ensure a safe and effective experience with your NO. BVN & BVW BORDERVEX REPLACEMENT CUTTER. Thank you for your attention to safety!

About Us

Brownells Europe

Brownells Europe - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

P.O.Box 4300
Warwick
CV34 9BR

www.brownells.eu