

KG 12 COPPER SOLVENT - KG PRODUCTS 4 OZ BIG BORE CLEANER

[Gun Cleaning & Chemicals](#) > [Solvents & Degreasers](#) > [Bore Solvents](#)

Essential Cleaner & Protectant Extends Firearm Life & Improves Function

Water-based, ammonia-free formula gently loosens copper buildup and prepares the bore for final cleaning.



Attributes

- Name: [KG PRODUCTS 4 OZ BIG BORE CLEANER](#)
- Manufacturer: [KG PRODUCTS](#)
- Product no.: 665000009
- Mfr. No.: D4-612
- Size: 4 oz
- Delivery weight: 0.136kg
- Shipping height: 178mm
- Shipping width: 53mm
- Shipping length: 48mm
- UPC: 695134006129

Item details

Made in USA

Table of Contents

- Startpage
- KG 12 Copper Solvent Safety Instructions
- About Us

KG 12 Copper Solvent Safety Instructions

Introduction

Thank you for choosing the KG 12 Copper Solvent. This product is designed to effectively clean copper buildup and prepare your bore for final cleaning. Your safety is our priority, and we have provided this guide to ensure the safe use of our product in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Always read the label and product information before use.
- Keep out of reach of children and pets.
- Use in a wellventilated area to avoid inhalation of vapors.
- Avoid contact with skin and eyes. If contact occurs, rinse thoroughly with water.
- Do not ingest. If swallowed, seek medical attention immediately.
- Store in a cool, dry place away from direct sunlight and heat sources.
- Follow all local regulations for disposal of chemical products.

Specific Safety Precautions for Use

- Ensure the area is free of any ignition sources when using the solvent.
- Wear protective gloves and eyewear to prevent skin and eye contact.
- Do not mix with other cleaning products or chemicals.
- Test the product on a small, inconspicuous area before full application to ensure compatibility with your materials.
- If you experience dizziness, headaches, or any adverse reactions, stop using the product immediately and seek fresh air.

Instructions for Installation and Usage

1. Preparation:

- Ensure the bore is free from any obstructions.
- Shake the bottle well before use to mix the contents.

2. Application:

- Apply a small amount of the solvent directly onto the bore using a suitable applicator.
- Allow the solvent to sit for a few minutes to loosen copper buildup.
- Use a cleaning brush or patch to scrub the bore gently.

3. Final Cleaning:

- After scrubbing, wipe the bore with a clean cloth or patch.
- Rinse the bore with water to remove any remaining solvent and copper residue.
- Dry the bore thoroughly before storing or using the item again.

4. PostUse Care:

- Clean any applicators or brushes used during the application with soap and water.
- Ensure the cap is securely closed after use to prevent evaporation and contamination.

Disposal Instructions

- Dispose of any unused product and empty containers in accordance with local regulations.
- Do not pour down drains or into the environment.
- Check for any specific disposal instructions on the product label.

Contact Information for Further Support

For any safety inquiries or additional information regarding this product, please refer to the contact information provided on the product packaging or visit the manufacturer's website.

Thank you for your attention to these safety instructions. Your careful use of the KG 12 Copper Solvent will ensure effective cleaning and maintain a safe environment.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk