

POWDER MEASURE BAFFLE - REDDING POWDER MEASURE BAFFLE

[Reloading](#) > [Powder Handling](#) > [Measure Stands & Accessories](#)

Redding powder measure baffel maintains a constant amount of powder above the metering chamber regardless of the level of powder in the reservoir



Attributes

- Name: [REDDING POWDER MEASURE BAFFLE](#)
- Manufacturer: [REDDING](#)
- Product no.: 749000379
- Mfr. No.: 03080
- Delivery weight: 0.032kg
- Shipping height: 38mm
- Shipping width: 51mm
- Shipping length: 51mm
- UPC: 611760030802

Item details

Made in USA

Table of Contents

- Startpage
- Redding Powder Measure Baffle Safety Instruction Guide
- About Us

Redding Powder Measure Baffle Safety Instruction Guide

Introduction

Thank you for choosing the Redding Powder Measure Baffle. This product is designed to maintain a constant amount of powder above the metering chamber, ensuring accurate measurements regardless of the powder level in the reservoir. To ensure safe and effective use of this product, please read and follow these safety instructions carefully.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage.
- Do not use the product if it is damaged or malfunctioning.
- Always follow the manufacturer's instructions for use and maintenance.
- Report any unsafe products or accidents to the appropriate authorities.
- Stay informed about product recalls by checking the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Always use the baffle in a wellventilated area to avoid inhaling dust particles.
- Avoid overfilling the powder reservoir to prevent spills and potential hazards.
- Do not attempt to modify or alter the product in any way.
- Ensure that the baffle is securely attached to the powder measure before use.
- Use appropriate personal protective equipment (PPE) such as safety glasses and gloves when handling powder.
- Keep the work area clean and organized to prevent accidents.

Instructions for Installation and Usage

1. Installation:

- Place the powder measure on a stable and level surface.
- Ensure that the powder reservoir is clean and free from any obstructions.
- Attach the baffle securely to the top of the powder measure, ensuring a snug fit.

2. Usage:

- Fill the powder reservoir with the appropriate powder for your intended use.
- Allow the baffle to settle and stabilize before taking measurements.
- Use the measuring device to dispense the desired amount of powder, ensuring that the baffle remains in place during operation.
- After use, empty any remaining powder from the reservoir and clean the baffle and measure thoroughly.

Disposal Instructions

- Dispose of the product in accordance with local regulations.
- Do not dispose of the product in household waste if it contains hazardous materials.
- Consider recycling options if available in your area.

Contact Information for Further Support

For any safety inquiries or further assistance regarding the Redding Powder Measure Baffle, please refer to the manufacturer's contact information provided with your product packaging.

Thank you for your attention to these safety instructions. By following these guidelines, you can ensure a safe and effective experience with your Redding Powder Measure Baffle.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk