

LOCK-N-LOAD POWDER MEASURE DRAIN TUBE - HORNADY LOCK-N-LOAD DRAIN TUBE INSERT

[Reloading](#) > [Powder Handling](#) > [Measure Stands & Accessories](#)

Swaps with metering inserts so you can drain powder without removing the measure from its stand. Compatible with Bench Rest Grade Powder Measure.



Attributes

- Name: [HORNADY LOCK-N-LOAD DRAIN TUBE INSERT](#)
- Manufacturer: [HORNADY](#)
- Product no.: 749002075
- Mfr. No.: 050125
- Delivery weight: 0.034kg
- Shipping height: 51mm
- Shipping width: 76mm
- Shipping length: 178mm
- UPC: 090255501254

Item details

Made in USA

Table of Contents

- Startpage
- LOCKNLOAD POWDER MEASURE DRAIN TUBE SAFETY INSTRUCTIONS
- About Us

LOCKNLOAD POWDER MEASURE DRAIN TUBE SAFETY INSTRUCTIONS

Introduction

Thank you for choosing the LOCKNLOAD POWDER MEASURE DRAIN TUBE by Hornady. This product is designed to enhance your powder measuring experience by allowing you to drain powder without removing the measure from its stand. Please read this safety instruction guide carefully to ensure safe and effective use of the product.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Always read the manufacturer's instructions and safety guidelines before use.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for any signs of wear or damage before each use.
- If you notice any defects or malfunctions, discontinue use immediately and contact the manufacturer.
- Report any unsafe products or accidents to the appropriate authorities.

Specific Safety Precautions for Use

- Always ensure that the powder measure is securely attached to its stand before use.
- Use the drain tube only with compatible powder measures to avoid leaks or spills.
- Do not attempt to modify the drain tube or the powder measure in any way.
- Avoid using the product in wet or damp conditions to prevent electrical hazards.
- Do not exceed the recommended capacity of the powder measure.
- Use personal protective equipment (PPE) such as safety glasses and gloves when handling powders.

Instructions for Installation and Usage

1. Installation:

- Ensure the powder measure is turned off and empty before installation.
- Remove the existing metering insert from the powder measure.
- Insert the LOCKNLOAD DRAIN TUBE into the powder measure, ensuring it fits securely.
- Confirm that the drain tube is properly aligned and locked in place.

2. Usage:

- To drain powder, tilt the powder measure slightly to allow the powder to flow through the drain tube.
- Monitor the draining process to avoid overfilling or spills.
- Once the desired amount of powder is drained, remove the drain tube carefully.
- Replace the metering insert back into the powder measure after use.

3. Maintenance:

- Clean the drain tube after each use to prevent residue buildup.
- Store the drain tube in a cool, dry place when not in use.

Disposal Instructions

- Dispose of the product in accordance with local regulations for nonfood products.
- Do not dispose of the product in regular household waste if it contains any hazardous materials.

- Consider recycling options if available.

Contact Information for Further Support

For any questions or concerns regarding the LOCKNLOAD POWDER MEASURE DRAIN TUBE, please contact the manufacturer directly. They can provide assistance and address any safety inquiries.

Please remember that your safety is paramount. By following these guidelines and instructions, you can ensure a safe and effective experience with your LOCKNLOAD POWDER MEASURE DRAIN TUBE. Thank you for your attention to these important safety measures.

About Us

Brownells Česká republika

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.cz