

# RCBS/HORNADY DROP TUBE ADAPTER - SINCLAIR INTERNATIONAL

## RCBS/HORNADY DROP TUBE ADAPTER

[Reloading](#) > [Powder Handling](#) > [Measure Stands & Accessories](#)

These Drop Tube Adapters are the adapters needed to allow your RCBS or Hornady powder measures to accept the Sinclair Custom Drop Tubes. Machined from stainless steel, these adapters replace your existing drop tubes and allow you to use Custom Drop Tubes of various lengths.



### Attributes

- Name: [SINCLAIR INTERNATIONAL RCBS/HORNADY DROP TUBE ADAPTER](#)
- Manufacturer: [SINCLAIR INTERNATIONAL](#)
- Product no.: 749002916
- Mfr. No.: 111550
- Delivery weight: 0.05kg
- Shipping height: 1mm
- Shipping width: 83mm
- Shipping length: 146mm

### Item details

Made in USA

# Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for RCBS/HORNADY DROP TUBE ADAPTER](#)
- [About Us](#)

# Safety Instruction Guide for RCBS/HORNADY DROP TUBE ADAPTER

## Introduction

Thank you for purchasing the RCBS/Hornady Drop Tube Adapter from Sinclair International. This guide provides essential safety information and instructions to ensure the proper use and maintenance of your product. Please read this guide carefully before using the Drop Tube Adapter.

## General Safety Guidelines

- Ensure that the Drop Tube Adapter is used only with compatible RCBS or Hornady powder measures.
- Always inspect the adapter for any signs of damage or wear before each use.
- Keep the product out of reach of children and vulnerable individuals.
- Use the Drop Tube Adapter in a wellventilated area to avoid inhaling any powder particles.
- Do not exceed the manufacturer's recommended load limits when using the adapter.
- Report any unsafe conditions or product malfunctions to the appropriate authorities.

## Specific Safety Precautions for Use

- Always wear appropriate safety gear, including safety glasses and a dust mask, when handling powder measures and adapters.
- Avoid using the adapter in wet or damp conditions to prevent rust and corrosion.
- Ensure that the adapter is securely attached to the powder measure before use.
- Do not force the adapter into position; if it does not fit, stop and check for compatibility.
- Keep hands and other body parts away from moving parts during operation.
- Never leave the product unattended while in use.

## Instructions for Installation and Usage

### 1. Installation

- Ensure that the powder measure is clean and free from any obstructions.
- Align the Drop Tube Adapter with the opening of the powder measure.
- Gently push the adapter into place until it is securely fitted. Do not use excessive force.
- Check that the adapter is stable and does not wobble or move.

### 2. Usage

- Fill the powder measure with the appropriate powder, ensuring it does not exceed the maximum fill line.
- Operate the powder measure according to the manufacturer's instructions.
- Monitor the flow of powder through the Drop Tube Adapter during use.
- After use, empty any remaining powder from the measure and clean the adapter thoroughly.

## Disposal Instructions

- Dispose of the Drop Tube Adapter in accordance with local regulations.
- If the product is damaged beyond repair, ensure it is disposed of in a way that prevents any potential harm to the environment.
- Recycle any materials if applicable, following local recycling guidelines.

## **Contact Information for Further Support**

For any inquiries or concerns regarding the RCBS/Hornady Drop Tube Adapter, please refer to the manufacturer's contact information provided with your product packaging or visit their official website for further assistance.

Thank you for choosing the RCBS/Hornady Drop Tube Adapter, and for taking the time to read this safety instruction guide. Your safety and satisfaction are our top priorities.

# About Us

## Brownells UK

### **Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories**

Unit 1, Laughing Dog Industrial Estate  
London Road  
Rugby  
Warwickshire  
CV23 9LP

[www.brownells.co.uk](http://www.brownells.co.uk)