

.001 DIAL INDICATOR - SINCLAIR INTERNATIONAL DIAL INDICATOR, .001

[Reloading](#) > [Case Preparation](#) > [Neck Turning](#) > [Neck Turning Accessories](#)

This dial indicator is dependable, a great value, and will provide great service to most reloaders. This is the work-horse indicator we provide with each of our measuring tools. Instant Indicators to use with Dial Indicator.



Attributes

- Name: [SINCLAIR INTERNATIONAL DIAL INDICATOR, .001](#)
- Manufacturer: [SINCLAIR INTERNATIONAL](#)
- Product no.: 749003991
- Mfr. No.: 3033111N
- Delivery weight: 0.204kg
- Shipping height: 58mm
- Shipping width: 84mm
- Shipping length: 155mm

Table of Contents

- [Startpage](#)
- [Safety Instruction Guide for .001 DIAL INDICATOR](#)
- [About Us](#)

Safety Instruction Guide for .001 DIAL INDICATOR

Introduction

Thank you for choosing the .001 DIAL INDICATOR from Sinclair International. This guide provides essential safety information and instructions to ensure the safe and effective use of this product. Please read this guide carefully before using the dial indicator.

General Safety Guidelines

- Always use the product as intended and in accordance with this manual.
- Ensure that the work area is clean, welllit, and free from obstructions.
- Keep the dial indicator away from children and unauthorized users.
- Regularly inspect the dial indicator for any signs of damage or wear before use.
- If the dial indicator is damaged, discontinue use immediately and seek assistance.
- Report any unsafe products or accidents to the appropriate authorities.
- Stay informed about product recalls through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- Avoid using the dial indicator in wet or damp conditions to prevent electrical hazards.
- Do not apply excessive force when taking measurements to avoid damaging the indicator.
- Ensure that the dial indicator is securely mounted before taking measurements.
- Use protective eyewear if there is a risk of flying debris during measurement activities.
- Keep hands and other body parts clear of moving parts during operation.
- Follow all local regulations regarding the use of measuring tools.

Instructions for Installation and Usage

1. Installation:

- Choose a stable surface for mounting the dial indicator.
- Securely attach the dial indicator to the measuring tool or surface using appropriate fastening methods.
- Ensure that the indicator is level and properly aligned for accurate measurements.

2. Usage:

- Turn on the dial indicator and allow it to calibrate if necessary.
- Gently position the measuring probe against the object to be measured.
- Read the measurement on the dial face carefully, ensuring that no external forces are applied during the reading.
- After use, turn off the dial indicator to conserve battery life if applicable.

Disposal Instructions

- Dispose of the dial indicator in accordance with local regulations for electronic waste.
- Do not dispose of the product in general household waste.
- Consider recycling options available in your area to ensure environmentally friendly disposal.

Contact Information for Further Support

For any questions or concerns regarding the use or safety of the .001 DIAL INDICATOR, please refer to the

manufacturer's contact information provided with the product.

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk