

LOCK-N-LOAD POWDER MEASURE STAND - HORNADY LOCK-N-LOAD FAST LOAD POWDER MEASURE STAND

[Reloading](#) > [Powder Handling](#) > [Measure Stands & Accessories](#)

The incredibly strong Fast-Load Powder Measure Stand has a rigid frame and extra long arm that lets you fill an entire 50-count Universal Loading Block. Accepts any measure with 7/8"-14 thread. Lock-N-Load Bushings: If you have more than one powder measure, you can switch them in and out of the Fast-Load stand in just seconds, using Lock-N-Load bushings. Long Reach: Lets you bench-mount the powder measure and still drop powder in the loading block.



Attributes

- Name: [HORNADY LOCK-N-LOAD FAST LOAD POWDER MEASURE STAND](#)
- Manufacturer: [HORNADY](#)
- Product no.: 749004511
- Mfr. No.: 050008
- Delivery weight: 0.658kg
- Shipping height: 109mm
- Shipping width: 163mm
- Shipping length: 221mm
- UPC: 090255500080

Item details

Made in USA

Table of Contents

- Startpage
- LOCKNLOAD POWDER MEASURE STAND SAFETY INSTRUCTIONS
- About Us

LOCKNLOAD POWDER MEASURE STAND SAFETY INSTRUCTIONS

Introduction

Thank you for choosing the Hornady LockNLoad FastLoad Powder Measure Stand. This product is designed to enhance your reloading experience by providing a stable and efficient way to measure and dispense powder. To ensure your safety and the safety of others while using this product, please read and follow these safety instructions carefully.

General Safety Guidelines

- Ensure that the product is used only for its intended purpose.
- Always keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the product for wear and damage before each use.
- Report any unsafe conditions or accidents to the appropriate authorities.
- Stay informed about product recalls through the EU's Safety Gate platform.

Specific Safety Precautions for Use

- **Hazard Identification:**

- The powder measure stand may cause injury if not used properly.
- Improper handling of powders can lead to fire hazards.

- **Avoiding Hazards:**

- Always use the stand on a stable and level surface.
- Do not exceed the recommended weight limit of the stand.
- Avoid using the stand near open flames or heat sources.
- Ensure that the powder measure is securely attached to the stand before use.

- **Age and Audience Specific Warnings:**

- This product is not intended for use by individuals under the age of 18 without adult supervision.
- Ensure that all users are informed about the correct handling of reloading materials.

Instructions for Installation and Usage

1. Installation:

- Place the FastLoad Powder Measure Stand on a stable, flat surface.
- Ensure that all components are intact and free from damage.
- Attach the powder measure to the stand using the 7/8"14 threaded connection, ensuring it is securely fastened.

2. Usage:

- To load powder, ensure the stand is stable and the powder measure is in a comfortable position.
- Use LockNLoad bushings if you have multiple powder measures to switch them in and out easily.
- Fill the loading block while ensuring the powder measure is positioned correctly to avoid spills.
- After use, clean the powder measure and stand to prevent residue buildup.

Disposal Instructions

- Dispose of the product in accordance with local waste disposal regulations.
- Do not dispose of powder or hazardous materials in regular trash. Follow local guidelines for hazardous waste disposal.

Contact Information for Further Support

For any safety inquiries or support, please contact the designated EUbased contact point for this product. Ensure you have the product details available for a more efficient response.

Thank you for your attention to these safety instructions. Enjoy your reloading experience with the Hornady LockNLoad FastLoad Powder Measure Stand.

About Us

Brownells Česká republika

Brownells - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

www.brownells.cz