

BR Feet

[Shooting Accessories](#) > [Shooting Rests](#) > [Rifle Rests](#)

BR Feet are designed to provide a stable, non-marring solution that keeps the spiked metal feet of your Rock BR from gouging or scratching the top of your shooting bench. BR Feet are rubber-coated, metal washer that allow the shooting rest's spiked metal feet to nest in the washer and provide a firm, no-slip footprint while protecting your tabletop.

NO IMAGE
AVAILABLE

Attributes

- Name: [BR Feet](#)
- Manufacturer: [Caldwell](#)
- Product no.: EU1001842
- Mfr. No.: 845221
- Delivery weight: 0.05kg
- Shipping height: 102mm
- Shipping width: 5mm
- Shipping length: 152mm
- UPC: 661120452218

Table of Contents

- Startpage
- Caldwell BR Feet Safety Instruction Guide
- About Us

Caldwell BR Feet Safety Instruction Guide

Introduction

Thank you for choosing Caldwell BR Feet. These rubbercoated, metal washers are designed to provide a stable, nonmarring solution for your Rock BR shooting rest. This guide outlines important safety instructions to ensure safe and effective use of the product, in compliance with the EU General Product Safety Regulation (GPSR).

General Safety Guidelines

- Ensure that the BR Feet are used only with compatible shooting rests to prevent instability.
- Always inspect the BR Feet before each use for any signs of wear or damage.
- Keep the product out of reach of children and vulnerable individuals to prevent accidents.
- Report any unsafe conditions or incidents to the appropriate authorities.

Specific Safety Precautions for Use

- Ensure that the shooting bench is stable and secure before placing the shooting rest on it.
- Avoid using the BR Feet on uneven surfaces to prevent tipping or slipping.
- Do not exceed the weight limit of your shooting rest while using the BR Feet.
- Always use the BR Feet in accordance with the manufacturer's guidelines to avoid potential hazards.

Instructions for Installation and Usage

1. Installation of BR Feet:

- Ensure that the shooting rest is turned upside down for easy access.
- Align the spiked metal feet of the shooting rest with the openings of the BR Feet.
- Gently press the spiked metal feet into the rubbercoated washers until they are securely nested.

2. Using the Shooting Rest with BR Feet:

- Place the shooting rest on a flat and stable surface.
- Ensure that the BR Feet are fully engaged with the shooting rest's feet to provide a firm, noslip footprint.
- Adjust the position of the shooting rest as needed for optimal stability.

3. PostUse Care:

- After use, remove the shooting rest from the BR Feet and clean any debris from the washers.
- Store the BR Feet in a dry place away from direct sunlight to maintain their integrity.

Disposal Instructions

- Dispose of the BR Feet in accordance with local regulations for rubber and metal waste.
- Do not dispose of the product in household waste. Check for recycling options in your area.

Contact Information for Further Support

For any safety inquiries or additional support, please refer to the manufacturer's contact information, which can be found on the product packaging or the manufacturer's website.

By following these guidelines, you can ensure a safe and effective experience with your Caldwell BR Feet. Thank you for your attention to safety!

About Us

Brownells UK

Brownells UK - World's Largest Supplier of Gun Parts, Gunsmith Tools & Shooting Accessories

Unit 1, Laughing Dog Industrial Estate
London Road
Rugby
Warwickshire
CV23 9LP

www.brownells.co.uk